



PERFORMANCE ANALYSIS COMPANY

969 OAK RIDGE TURNPIKE, SUITE 258
OAK RIDGE, TN 37830

865-482-9175
(Voice or FAX)

AUTOTEMP II CLIMATE CONTROL SERVOS for Chrysler & Imperial Automobiles

**Assembled with ALUMINUM housing
Will not crack or leak**

CALIBRATED AND TESTED TO EXACT OEM SPECIFICATIONS



**Price: \$595 exchange - we accept Visa/MC
CALL or FAX number above or E-mail:
perfanalysis@comcast.net**

If your servo is cracked, it will cease functioning soon...the antifreeze residue will foul the gears inside the unit and it will seize up. Your battery may go dead for no apparent reason if the servo is stuck outside the PARK position.

If you don't replace the servo when it seizes up, it will eventually burn up the amplifier (\$99 from us).

We manufacture an aluminum climate control servo that will not crack and leak like the OEM units do after 2 or 3 years. It is an exact replacement for the OEM unit. These rebuilt aluminum units are warranted for 1 year with a \$95 charge to repair thereafter.

REBUILT ALUMINUM SERVO \$595

Remanufactured units using aluminum upper body; assembled with new gaskets and seals; fully tested and calibrated. Exact replacement for original equipment. Initial one-year full replacement warranty; only \$95 to repair thereafter. (\$75 core charge)

CLIMATE CONTROL AMPLIFIERS - NEW \$99; Rebuilt \$69 exchange

Replacement recommended if servo has failed or existing unit is more than 6 years old - restores proper system response.

